

1/10




Fig. 1A

TOP VIEW





Fig. 1B

SIDE VIEW



— HORSESHOE VORTEX
--- WAKE VORTEX

Fig. 1C





Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8





Fig. 9



10/10

Report of Event Screen

File Edit View Go Favorites Help

500-Year Event
100-Year Event
50-Year Event
10-Year Event

00014
00183
00271
00305
00431
02350
02366
02411
03482
03527
03601

Report of 50-Year Event
Start Date 05/17/98
Time: 5:00 a.m.
Duration: 11:24:36

Bridge Information Detail
Inspector's Comments:
Actions Taken:

1000

Toggle Radar
Search for Bridge
Sort List
Bridge History
Send Report
Search for Report

Fig. 10